Appendix E Photograph Log



Photograph 1. County Road Project No. 5696 – View of staging area located northeast of the Wollochet Drive Northwest and East Bay Drive Northwest intersection.



Photograph 2. County Road Project No. 5696 – Containers of pipe lubricant stored outdoors without coverage or containment BMPs.



Photograph 3. County Road Project No. 5696 – Close-up view of label on pipe lubricant.




Photograph 4. County Road Project No. 5696 – View of standing water in the drainage ditch at the southwest corner of the staging area. Note that the drainage pipe conveys flow under Wollochet Drive Northwest.



Photograph 5. County Road Project No. 5696 – View of portable toilet southwest of the staging area along Wollochet Drive Northwest.



Photograph 6. County Road Project No. 5696 – Close-up view of portable toilet that was not properly secured.



Photograph 7. Central Maintenance Facility – View of sand bags and absorbent socks around base of containment for salt storage. Note salt seeping through cracks.



Photograph 8. Central Maintenance Facility – View of sediment tracking outside the Equipment Services Division's wash area.

Inspection Dates: May 15-16, 2012




Photograph 9. Central Maintenance Facility – View of sediment accumulation inside the asphalt emulsion containment area.



Photograph 10. Central Maintenance Facility – View of containment drain valve without a lock at the secondary containment for the brine tanks.



Photograph 11. Central Maintenance Facility – View of containment drain valve without a lock at the secondary containment for the asphalt emulsion tanks.



Photograph 12. Remann Hall Juvenile Facility – View of leachate fromt the garbage container on the west side of the Facility.



Photograph 13. Remann Hall Juvenile Facility – View of soil stockpile without BMPs for erosion and sediment control in the parking lot near Progress House.



Photograph 14. Remann Hall Juvenile Facility – Close-up view of oil staining in the vehicle and equipment maintenance and storage area.



Photograph 15. Remann Hall Juvenile Facility – View of oil stains in the vehicle and equipment maintenance and storage area.